



# SERVICE PARTS LIST

**BULLETIN NO.**  
**54-04-0010**

SPECIFY CATALOG NO. AND SERIAL NO. WHEN ORDERING PARTS			REVISED BULLETIN	DATE
<b>M12™ and M18™ Multi Voltage Battery Charger</b>				Jan. 2013
<b>CATALOG NO.</b>	<b>48-59-1812</b>	<b>SERIAL NUMBER</b>	<b>D63A</b>	
			WIRING INSTRUCTION	

**EXAMPLE:**  

00	0
----	---

 Component Parts (Small #)  
 Are Included When Ordering  
 The Assembly (Large #).




FIG.	PART NO.	DESCRIPTION OF PART	NO. REQ.
1	12-20-1812	Service Nameplate	(1)

**FIG. NOTES**

1 A clean, dry surface is essential for proper performance for any adhesive system. The area intended for application of any adhesive label or nameplate must be prepared by cleaning with isopropyl alcohol. The solvent is to be applied with a clean, lint free applicator and the surface allowed to dry before applying the label or nameplate.



# SERVICE PARTS LIST

**BULLETIN NO.**  
**54-04-0010**

SPECIFY CATALOG NO. AND SERIAL NO. WHEN ORDERING PARTS			REVISED BULLETIN	DATE
<b>M12™ and M18™ Multi Voltage Battery Charger</b>				Jan. 2013
<b>CATALOG NO.</b>	<b>48-59-1812</b>	<b>SERIAL NUMBER</b>	<b>D63A</b>	
WIRING INSTRUCTION				

**EXAMPLE:**  

00	0
----	---

 Component Parts (Small #)  
 Are Included When Ordering  
 The Assembly (Large #).




FIG.	PART NO.	DESCRIPTION OF PART	NO. REQ.
1	12-20-1812	Service Nameplate	(1)

**FIG. NOTES**

1 A clean, dry surface is essential for proper performance for any adhesive system. The area intended for application of any adhesive label or nameplate must be prepared by cleaning with isopropyl alcohol. The solvent is to be applied with a clean, lint free applicator and the surface allowed to dry before applying the label or nameplate.